Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BB-BELQUIST- 150-95-1110H-9

Field Name: BLUE BUTTES Well File #: 28919

Date Incident: 12/4/2014 Time Incident: 11:00 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 95 Sec: 11 Qtr: NE SE

Location Description: From Hwy 22 travel to 31St NW turn south on 103rd Ave NW

Submitted By: Troy Brunsell Received By:

Contact Person: Jason Henry

1501 MCKINNEY

HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 2 Barrels 2 Barrels

Description of Other Released Contaminant:

Oil Base Mud

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No immediate risk to report.

Areal Extent:

Potential Environmental Impacts:

Location soil under liner.

Action Taken or Planned:

Drilling operation shut down to cleanup the OBM on the liner. Repairs made to shakers while shut process was in place.

Wastes Disposal Location: OBM was recovered and used during drilling operations.

Agencies Involved:

Updates

Date: 12/5/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.